

Inspection of Sanitation Report of District Yamuna Nagar

1.	Name of the School	GANPATI CONVENT SCHOOL
		VILLAGE - PANDON
2.	Sanitation Condition	
	(a) Area of location	PANDON
	(b) No. of rooms	12 ROOMS
	(c) Height of ceiling	11½ FEET
	(d) No. of air fans	48 FAN
	(e) No. of exhaust fans	4 TOILET
	(f) Light emergency power supply <u>AVAILABLE</u>	GENERATOR FACILITY
	(g) Total no. of Strength	180
3.	Total no. of Urinals	4 Toilets 9
4.	Water Supply--- Public Health/Ground water	BOTH
5.	Chlorination	yes
6.	First Aid Box with Medicines	yes
7.	Protection of lighting	UNDER PROCESS
8.	No. of Dustbins	12
9.	No. of Sweepers	4

Dist. No - 397

Dated 28/04/2023

Pooja Tripathi
Headmistress
Ganpati Convent School
Barara Road, Sadhaura
Distt. Yamunanagar

[Signature]
Ganpati Convent School
Chairman

[Signature]
HCMS-1
Senior Medical Officer
CHC Sadhaura (YNR)
[Signature]
CHC Sadhaura